





UV-VIS
 ABSORPTION
 (needs to have color)
 (dyes)

EMISSION
 (must fluoresce or phosphoresce)
 (T-gases)



FTIR

must have:
 the double CO₂, D₂O



AAS (metals)

AE, ICP (metals +)

